

Pressure Conversion Chart

PSI	kPa	BAR
1	6.89	0.07
10	68.95	0.69
20	137.90	1.38
30	206.84	2.07
40	275.79	2.76
50	344.74	3.45
60	413.69	4.14
70	482.64	4.83
80	551.58	5.52
90	620.53	6.21
100	689.48	6.90
125	861.85	8.62
150	1034.22	10.34
175	1206.59	12.07
200	1378.96	13.79
225	1551.33	15.51
250	1723.70	17.24
275	1896.07	18.96
300	2068.44	20.69
325	2240.81	22.41
350	2413.18	24.13
375	2585.55	25.86
400	2757.92	27.58
425	2930.29	29.30
450	3102.66	31.03
475	3275.03	32.75
500	3447.40	34.48
525	3619.77	36.20
550	3792.14	37.92
575	3964.51	39.65
600	4136.88	41.37
625	4309.25	43.09
650	4481.62	44.82
675	4653.99	46.54
700	4826.36	48.27
725	4998.73	49.99
750	5171.10	51.71

Psi	kPa	BAR
775	5343.47	53.44
800	5515.84	55.16
825	5688.21	56.88
825	5860.58	58.61
875	6032.95	60.33
900	6205.32	62.06
925	6377.69	63.78
950	6550.06	65.50
975	6722.43	67.23
1000	6894.80	68.95
1100	7584.28	75.85
1200	8273.76	82.74
1300	8963.24	89.64
1400	9652.72	96.53
1500	10342.20	103.43
1600	11031.68	110.32
1700	11721.16	117.22
1800	12410.64	124.11
1900	13100.12	131.01
2000	13789.60	137.90
2500	17237.00	172.38
3000	20684.40	206.85
3500	24131.80	241.33
4000	27579.20	275.80
4500	31026.60	310.28
5000	34474.00	344.75
5500	37921.40	379.23
6000	41368.80	413.70
6500	44816.20	448.18
7000	48263.60	482.65
7500	51711.00	517.13
8000	55158.40	551.60
8500	58605.80	586.08
9000	62053.20	620.55
9500	65500.60	655.03
10000	68948.00	689.50